



Environmental Monitoring and Technical Services
Water Quality Laboratory
ELAP Cert. 1058

City of San Diego
Water Quality Chemistry Services
Lead School Testing
March 13, 2017

Sample Date	Location	Sampling Site	State ID	CSD Sample ID	Units	Value	DLR
7-Mar-17	SDUSD SD COOP CHARTER #2	Room 128, bubbler in sink	3710020-AAD-B	W1158856	UG/L	38.6	5
7-Mar-17	SDUSD SD COOP CHARTER #2	Room 127, bubbler in sink	3710020-AAD-A	W1158855	UG/L	22.0	5
7-Mar-17	SDUSD SD COOP CHARTER #2	Room 130, bubbler in sink	3710020-AAD-E	W1158859	UG/L	<DLR	5
7-Mar-17	SDUSD SD COOP CHARTER #2	Room 129, bubbler in sink	3710020-AAD-D	W1158858	UG/L	<DLR	5
7-Mar-17	SDUSD SD COOP CHARTER #2	Room 132, bubbler in sink	3710020-AAD-C	W1158857	UG/L	<DLR	5
3-Mar-17	Emerson Elementary	Inside room 106, back right corner sink, drinking bubbler	3710020-AAC-D	W1158863	UG/L	<DLR	5
7-Mar-17	Emerson Elementary	Cafateria sink, near back left corner, pull down pot filler	3710020-AAC-B	W1159031	UG/L	<DLR	5
3-Mar-17	Emerson Elementary	Near room 115, between restrooms, right bubbler on double fountain	3710020-AAC-C	W1158862	UG/L	29.0	5
3-Mar-17	Emerson Elementary	Health Office, sink, faucet	3710020-AAC-A	W1158860	UG/L	<DLR	5
3-Mar-17	Emerson Elementary	Outside, right of room 107 between restrooms, drinking fountain, left bubbler	3710020-AAC-E	W1158864	UG/L	<DLR	5

DLR= State Mandated Detection Limit for Reporting
Action Level = 15 UG/L

Tom Burger, Associate Chemist